

TECHNCIAL NOTE no.: 53	
Product:	Electric harness inspection
Part number:	n/a
To:	Audi RS3 LMS Gen2 and Cupra Leon Competicion
Date:	19/03/2024

Dear customer,

As a cable crimping problem has been reported we are asking you to perform checks on the crimping of the power-box connectors.

The thin brown cables (Power-box ground supply and identification) need to be checked with caution if the crimping is correct and tight.

To perform the check, pull each thin brown cable firmly from behind to check if it's fixed to the pin correctly. Apply appropriate force to check the installation but not to rip out the cable by mistake.

In case of electrical malfunction these connections have to be checked first.

As a precaution it could be a good idea to check all 7 power-box connectors mounted in the car.

