



We advise rebuilding the actuator to 6000kms maximum.

The rebuild must be performed by XAP Technology, it is strictly forbidden to do it by yourself (seals are present on the actuator).

Price of the rebuild is 250€ excl VAT and shipping cost.

The price includes:

- Removing, cleaning and re-assembly of all the internal components.
- Bearings change.
- General inspection of each component.
- Performance control on a test bench.

Shipping address:

**XAP TECHNOLOGY SAS
ZAC DU VIGNE
2968 RUE DES ENTREPRENEURS
F-30420 CALVISSON**

Note :

Before sending the parts thanks to contact XAP :
corinnehardy@xap.fr or/and support@xap.fr for the delivery time.