



## TECHNICAL BULLETIN

<b>Product:</b>	Selector Rack Anti-rotation pin & washer				
<b>Reference No:</b>	CFT/004				
<b>To:</b>	CUPRA/AUDI				
<b>Author:</b>	JMB	<b>Date:</b>	01/09/2022	<b>Issue no.</b>	1

It should be noted that the washer (WSH-028) which sits under SCR-349 anti-rotation pin must be fitted. If this washer is omitted, the anti-rotation pin could cause the rack to stick. It should also be noted that using an incorrect specification washer could also have this effect. A washer no less than 1mm must be fitted (Hewland recommend only the correct WSH-028 is used)



*The contents of this document are confidential, not for public disclosure and are proprietary to Hewland Engineering Limited ('the Company'). No reproduction or copying of its contents are permitted. This document is for discussion purposes only and is therefore subject to change and amendment. The final contract between the Company and the client for whom this document has been prepared exclusively governs the provision of, and liability for, the information contained herein. The provision of this document does not imply any obligation on the part of the Company to update the contents thereof or to proceed with any particular aspect of the proposal, and the Company makes no warranty, implied or otherwise, as to the fitness for purpose of the contents herein. No partnership or joint venture is implied or formed by the provision of this document.*



Hewland Engineering Ltd  
Waltham Road, White Waltham  
Maidenhead, Berkshire  
SL6 3LR, UK

+44 (0) 1628 827600  
info@hewland.com  
www.hewland.com